Attorney Docket No. 1405.1017

THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Noriyuki FUKUYAMA et al.

Application No.: 09/520,810

: 09/520,810 ATTENTION

Confirmation No.: 2159 CERTIFICATE OF CORRECTION

Filed: March 8, 2000 BRANCH

U.S. Patent No.: 7,061,902

Issued: June 13, 2006

For: TELEPHONE COMMUNICATION SYSTEM AND METHOD FOR CONTROLLING THE

TELEPHONE COMMUNICATION SYSTEM

## REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Certificate

JAN 1 7 2007

<del>of Correction</del>

David M. Pitcher

Registration No. 25,908

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

PTO/SB/ 44 (08-00)
Approved for use through 09/30/2000. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
Also Form PTO-1050) (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,061,902 **DATED**: June 13, 2006

INVENTOR(S): Noriyuki FUKUYAMA et al.

In the specification:

Column 49, line 3, change "packet switched" to --packet-switched--

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. 7th Floor Washington, DC 20005

PATENT NO. 7,061,902

No. of add'l copies @ 50¢ per page